

Installation guide for Sprint Booster #SBAU0011, Audi A5/S5 2007+





Tools needed:


1. Small flat head screw driver.

Step 1- Turn off Ignition. Get yourself in position to work just above the gas pedal assembly. Your pedal area should similar to Fig #1




Step 2 – Remove the upper part of the cosmetic cover along the lowest part of the dash that is just above the gas and brake pedal. Shown more in Fig #2. It will not need to be totally removed, it only has to hang loose for the install of the Sprint Booster.






The highlighted shroud will remove with little effort, no tools are needed, a healthy downward pull will release it of its holding clips.

Step 3- Now that the small shroud is loose, you will see a connection with a red tab above the gas pedal. Fig #3



The red tab acts as a locking device for the connector to stay attached. Unlock the connection by pressing the red tab upwards.

Step 4- While keeping the cosmetic shroud out of the way, remove connection from the gas pedal. This is where the Sprint booster will be inserted. Get familiar with how the Sprint Booster should be plugged in. It will only install successfully in one direction. The fork in the Sprint Booster will face to the left and downward in the pedal. Proper installation is shown in Fig #4.



You may find the heating vents to obstruct the alignment of the Sprint Booster. The vents will move a bit to one side.

Step 5 – Also shown in Fig #4 is the OEM harness connection to the Sprint Booster. Plug in the harness to the Sprint Booster in the same position as it was installed on the pedal. Relock the connection with the red tab pressed downward.

Step 6- The Sprint Booster install is complete! Re-attach the plastic shroud removed in fig #2.

Go for a drive!



NOTE: If when you get the Sprint Booster and the pedal back together, and the car starts with no throttle response or the car revs erratically/high - be sure to check your harness and pedal connection. If your connection is secure without any bent harness pins upon inspection, there is either a malfunction within the Sprint Booster unit, or you have the incorrect part # for your application. Please contact your place of purchase for further assistance, or call 1 877 225 5577.



