

SPRINT

BOOSTER

POWER CONVERTER


Installation guide for Sprint Booster # SBCH0021, '09 Camaro.



Tools needed:

1. Flathead screwdriver

Step 1- Turn off Ignition. Get into position to work near the gas pedal. Look to the top of the gas pedal. It will have an electrical connection above where it fastens to the firewall. This is where the Sprint Booster will install, inline of the factory harness/pedal connection. On this particular connection, there is a grey safety clip that needs to be moved in order for the connection to be released. Fig #1 shows the motions the grey clip needs to go through to be released... first push upward, then second press the black center while pulling the harness away. The grey clip will always stay attached to the black connector. A flathead screwdriver may be of aid here.



www.jrponline.com

www.sprintboosterusa.com

The harness should now be free of the pedal as in Fig #2



Step 2- Once the harness is free of the pedal, place inline the Sprint Booster. Fig #3 shows the proper installation position with harness reattached and grey clip secured. When inserting the Sprint Booster, be careful not to use excessive force or misalign while pressing it in. This can damage the pins of the connector. The Sprint Booster will only connect in one direction to the pedal; the large tab on the Sprint Booster will face to the driver side and downward.



Step 3- Proceed to re-connect the harness, with Sprint Booster, into the pedal with the same precaution mentioned as Step 2. Make sure your OEM harness will have enough slack before reconnecting with the Sprint Booster fully installed. The harness may require a new route to give the needed freedom in the harness.

Now the install is complete!! Enjoy your new throttle response!!

NOTE:

If when you get the Sprint Booster and the pedal back together, and the car starts with no throttle response or the car revs erratically/high - be sure to check your harness and pedal connection. If your connection is secure without any bent harness pins upon inspection, there is either a malfunction within the Sprint Booster unit, or you have the incorrect part # for your application. Please contact your place of purchase for further assistance, or call 1 877 225 5577.

