



Right side  
adjustment shown

## Part No. 78090 – Saturn Rear Wheel Toe Adjusting Tool

### INSTRUCTIONS FOR USE:

1. Loosen the rear most inboard lateral-link-to-crossmember fastener for the rear wheel being adjusted.
2. Use the adjusting tool #78090 to move the lateral link either in or out as needed to adjust toe to correct specification.
3. Torque the lateral-link-to-crossmember fastener to manufacturer's specification.
4. Check alignment readings and test drive the vehicle.



### SPECIALTY PRODUCTS COMPANY

P.O. Box 923

Longmont, CO 80502-0923

1-800-525-6505 (USA only) • (303) 772-2103

Printed in U.S.A. • Rev. 11/97