

About Lanzar VW/VBPW Series Woofer

Congratulations!


You have just purchased one of the most advanced subwoofers in the history of car audio. Lanzar VW/VBPW Series Woofer is the latest series, which has been designed and engineered for consistent and high performance.

Let's enjoy the nice music that VW/VBPW Woofer provided.


Basic Features of Lanzar VW/VBPW Series Woofers:

- Black P.P Cone/None press paper (VBPW1236D)
- Specially Treated Foam Edge Suspension
- High Temperature Voice Coil
- Chromed Back Plate Cover (EXCEPT VBPW1236D)
- Rubber Magnet Boot Cover (EXCEPT VBPW1236D)


VW64




VW84




VW104/10D




VW124/12D



VW154/15D



VBPW1236D



Specification	VW64	VW84	VW104/10D	VW124/12D	VW154/15D	VBPW1236D
Power (Watts Peak)	600	800	1200	1600	2000	2000
Nom. Impedance (ohm)	4	4	4	4	4	4
Voice Coil	1.5"	1.5"	2.0"	2.5"	2.5"	3"
Magnet Structure	40	50	70	95	120	285
Fs (Hz)	80	60	50	40	30	30
Qms	4.05	4.08	4.92	5.0	5.0	6.0
Qes	1.3	1.2	0.84	0.90	0.90	0.8
Qts	1.2	1.1	0.72	0.75	0.75	0.7
SPL (dB)	87	88	85	84	89	90
Vas (cuft)	6.8	6.0	4.908	5.204	6.02	5.9

Lanzar VW/VBPW Series Woofer continually to improve the performance and value of its products- all specifications are subject to change.

MANUFACTURER'S LIMITED ONE YEAR WARRANTY

LANZAR INC. warrants this unit to be free from defective material or workmanship and will repair or replace this unit any parts belonging to this unit. only if proven that after normal use it was defective within one (1) years from the date of original purchase.

The item, when sent in for service should be accompanied by proof of purchase.

Our obligation under this warranty is limited to the repairing or replacing at our discretion, the defective instrument or any part there of when it is returned, transportation must be prepaid to the legacy Service Center at the address below. The return shipping fees are as follows if the entire enclosure is sent in there will be a fee of \$ 25.00 for return shipping, however we would suggest you would return only the defective speakers if that \$15.00. Be advised we are not responsible for cosmetic damage of the unit.

This warranty will be considered void, if the unit has been tampered in a commercial vehicle. This warranty does not cover accidental damage. All payment accompanying defective units should be by US money order or any other payment option must be authorized by our service center.

Send your unit to:

LANZAR SERVICE CENTER
1600-63RD Street
Brooklyn, New York 11204
1-718-236-8000
1-800-444-5671
www.lanzar.com

IMPORTANT

Pack carefully in original carton if possible. We are not responsible for damage incurred in returning items for repair. A letter stating your exact street address, daytime phone number, and a brief statement describing the problem you are experiencing to ensure proper repair of the unit in question.

Lanzar

SPECIFICATIONS



VW64 VW84 VW104/10D VW124/12D VW154/15D

WWW.LANZAR.COM